

A page number in italics indicates that a photograph or an illustration appears on that page.

- Abbreviations See Appendix B
- Adjacent views 286–300, 394–395, 286, 299–300, 394–395
- Aerospace engineering 10–12, *10–12*
- Aligned sections 354
- Alphabet 174–197, *174–197*
- Alphanumeric keyboard 86, 86
- American National Standards Institute (see ANSI)
- Angled surfaces 311–313, *311–313*
- Angle of inclination 316, 316
- Angles 202–203, 257–258, 263–267, 313, 421–432, 202–203, 257–258, 263–267, 313, 421–432
- Annotation 174–197, *174–197*
- ANSI (American National Standards Institute) 14–15, 95, 149–150, 286, 575–635, 149–150, 578–635
drawing sizes 149–150, *149–150*
lettering 174–197, *174–197*
Y14.5 (dimensioning) 515–570, 575–635, 516–569, 578–635
- Aperture card (see also COM) 131–132, 831, 838, *131–132*, 831, 839
design data cards 131–132, 831, *132*, 831
reading system 131–132, 831, *132*, 831
- Architect's scale 140–142, *140–142*
- ARC command 237, 532–537, 237, 532–537
- Architecture 10–11, 93–94, *11*, 93–94
- Architectural design 10–11, 93–94, *11*, 93–94
- Architectural, engineering, and construction (AEC) 10–11, 93–94, *11*, 93–94
- Arcs (see also *Isometric drawing*)
- ARRAY command 733–735, 959–960, 733–735, 959–961
- Arrowheads 524, 561, *524*, 561
- Arrows, section 342–373, *343–373*
- Assembly 810–850, *811–851*
adaptive 822–824, *822–824*
automatic 822–824, *822–824*
ballooning 822–824, *822–824*
- CAD, using 80, 82, 92–93, 287, 295, 822–824, 839–851, 82, 93, 287, 295, 822–824, 840–851
drawings 2, 7–8, 810–851, 7–8, *811–851*
hidden lines 306–307, 817, 306–307
parts list 820–824, *820–824*
view selection 286–306, *286–306*
exploded 812–851, *812–851*
flexible 812–851, *812–851*
manual 812–840, *813–841*
pictorials 812–851, *812–851*
revisions 829–830, *829–830*
sections 817, 832–851, 833–851
semiautomatic 812–851, *812–851*
welding 780–802, 812–833, 780–802, 812–833
- Automobile 820, 820
- Auxiliary views (see also *Descriptive geometry*) 9, 387–405, 9, 387–405
adjacent 286–300, 394–395, 286, 299–300, 394–395
broken 400–402, *400–402*
CAD 398–399, 402–405, 398–399, 402–405
conventions 308
front-adjacent 286–300, 286–300
frontal 286–300, 390–393, 286–300, 390–393
glass box theory 287–300, 287–300
horizontal 286–300, 392–393, 286–300, 392–393
partial 393–394, 393–394
primary 389–390, 389–390
profile 393–393, 393–394
reference plane method 395–397, 395–397
secondary 389–390, 394–396, 389–390, 394–396
sections 402, 402
side-adjacent 286–300, 286–300
successive 400–402, *400–402*
top-adjacent 286–300, 286–300
- Auxiliary view sections 362–373, 363–373
- Axes 273–276, 432–435, 273–276, 432–435
- Axonometric projection 420–433, 420–433
- BALLOON command 822–824, 822–824
- Ballooning 822–824, *822–824*
- Bar stock 481–482, 481–482
- Bearings 711, 735–738, 712, 736–738
ball 735–738, 736–738
 housings 738, 738
journal 735–738, 736–738
loading 735–738, 736–738
mountings 738, 738
plain 735–738, 736–738
roller 735–738, 736–738
thrust 735–738, 736–738
- Bend allowance 1001, 1001
- Bill of materials (see also *Parts list*) 820–824, 820–824
- Binary digit 84, 85
- Bisectors (see *Geometric constructions*) 207, 207
- Bits 84, 85
- Blocks 149–150, *149–150*
- Blueprint machine (see also *Whiteprint machine*) 132, 134, 831, *132*, 134, 831
- Blueprints 132, 134, 831, *132*, 134, 831
- Bolts 664–666, 664–666
- Borco vinyl 131–132, *131–132*
- Box method 286–305, 286–305
- Breaks, pictorials 367, 367–368
- Breaks, section 367, 367–368
- Broach 484, 484
- Broken-out sections 357–360, 357–360
- Brushes 134–136, 136
- Button box 80–87
- Button menus 80–87
- Byte 84

- Cabinet projection (see *Oblique projection*)
- CAD 3-4, 7, 14, 80, 82, 93, 103-128, 286-287, 295, 3, 7, 14, 93, 103-128, 287, 295
 - centerlines, using 305, 307, 305, 307
 - commands (see *Commands*)
 - descriptive geometry 9, 880-908, 916-937, 944-961, 9, 880-908, 916-937, 945-961
 - design 5-8, 19-27, 32-79, 7-8, 19-27, 32-79
 - developments 998-1023, 999-1023
 - dimensioning 517-519, 517-519
 - fasteners 662-689, 662-689
 - gears 711-738, 712-738
 - geometric construction 200-239, 200-239
 - lettering 174-197, 174-197
 - machining 110, 478-513, 840-851, 110, 478-513, 840-851
 - multiview projection 286-326, 286-326
 - revolution, 3D part 958-960, 958-961
 - pictorials 80-82, 447-463, 81, 447-463
 - sections 368-373, 368-373
 - springs 702-701, 702-704
 - threads 674-677, 674-677
 - tolerancing 622-625, 622-625
 - welding 780-802, 780-802
- CAD/CAM (see also *CAD*) 3-4, 7, 13-14, 82-84, 93, 98-100, 124-128, 192-197, 224-239, 280, 287, 295, 478-513, 3-4, 7-8, 13-14, 93, 98-100, 124-128, 192-197, 224-239, 478-513, 811
 - CNC 13-14, 80-84, 92, 93, 98-100, 124-128, 13-14, 81, 93, 98-100, 124-128
 - dies 484, 405-513, 840-851, 504-513, 840-851
 - fixtures 286, 504-513, 840-851, 504-513, 840-851
 - group technology 504-513, 840-851, 504-513, 840-851
 - manufacturing and machining 110, 478-513, 840-851, 110, 478-513, 840-851
 - finishing pass 505-513, 505-513
 - islands 505-513, 505-513
 - pocketing 505-513, 505-513
 - profiling 505-513, 505-513
 - rough cutting 505-513, 505-513
 - mold design 505-513, 505-513
 - NC (see *CNC*) 13-14, 81, 99-100, 110, 504-513, 13-14, 81, 99-100, 110, 504-513
 - process planning 504-505, 504-505
 - programming 505-513, 505-513
 - continuous path 505-513, 505-513
 - point-to-point 505-513, 505-513
 - quality control 504-513, 504-513
 - robotic 99-100, 511-513, 99-100, 511-513
 - library 99-100, 511-513, 99-100, 511-513
 - simulation 99-100, 511-513, 99-100, 511-513
 - workcell 99-100, 511-513, 99-100, 511-513
 - work envelope 99-100, 511-513, 99-100, 511-513
 - sheet metal 988-991, 1016-1018, 988-991, 1016-1018
 - shop layout 6-7, 812-850, 7, 813-851
 - software (see also *Software applications, Pro E*)
 - technical publications 6, 6
 - tool design 480, 480
 - tooling 480, 505-513, 841-851, 480, 505-513, 840-851
 - tool (cutter) path generations, 505-513, 840-851, 505-513
 - programming, simulation, and verification 505-513, 840-851, 505-513, 840-851
- CAE 13-14, 81, 99-100, 110, 504-513, 13-14, 81, 99-100, 110, 504-513
- CALCULATE AREA command 936, 936
- Calipers 490, 490
- CAM (see also *Computer aided manufacturing*) 80, 98, 98, 124-128, 478-513, 478-513
- Cams 742-755, 742-755
 - classes 745-747, 750, 745-747, 750
 - cycloidal motion 745-747, 750, 745-747, 750
 - harmonic motion 745-747, 750, 745-747, 750
 - parabolic motion 745-747, 750, 745-747, 750
 - uniform motion 745-747, 750, 745-747, 750
 - dimensioning 753-755, 753-755
 - displacement diagram 750-751, 750-751
 - drawing 752-755, 752-755
 - drum cam (cylindrical) 750-751, 750-751
 - flat plate cam 750-751, 750-751
 - followers 742, 750, 750-751
 - roller 750-752, 750-752
 - terms 743-745, 743-745
- Career, drafting 3-5, 10, 3-4
- Casting 322, 493-495, 322, 493-495
 - datum planes 493-495, 517, 493-495
 - details 322, 493-495, 322, 493-495
 - die 484, 493-495, 840-851, 493-495, 840-851
 - draft angle 493-495, 493-495
 - drawings 7, 493-495, 493-495
 - fillets 322, 447-463, 493-495, 322, 447-463, 493-495
 - gravity 493-495, 493-495
 - injection molding 493-495, 493-495
 - patterns 493-495, 493-495
 - pressure 493-495, 493-495
 - rounds 322, 493-495, 322, 493-495
 - sand 493-495, 493-495
 - taper 493-495, 541-542, 493-495, 541-542
 - tooling points 493-495, 505-513, 840-851, 493-495, 505-513, 840-851
- Catalog parts 840-851, 840-851
- Cavalier projection (see *Oblique projection*)
- Centerlines 305, 307, 307, 307
- Chamfer 228-232, 540-541, 228-232, 540-541
- Checker 3-4, 4
- CIM (computer integrated manufacturing) 13, 80-81, 87, 499, 13, 87, 499
- CIRCLE command 235-237, 235-237
- Circles 263-267, 421-432, 263-267, 421-432
 - in isometric 421-432, 421-432
- Civil engineer 10-11, 95, 11, 95
- Civil engineer's scale 139-141, 139-141
- Civil engineering 10-11, 95, 139-141, 11, 95, 139-141
- Collars 682, 684
- COLOR command 984-987, 984-987
- Commands (CAD) 224-239, 224-239
 - ARC command 237, 237
 - ARRAY command 733-735, 959-960, 733-735, 959-961
 - BALLOON command 822-824, 822-824
 - CIRCLE command 235-237, 235-237
 - CLOSE command 130
 - COLOR command 984-987, 984-987
 - CUT PLANE command 371-373, 983-987, 371-373, 983-987
 - DIMENSION command 174, 563, 563
 - DISTANCE command 907-908, 907-908
 - DRAW LINE command 233-235, 907-908, 233-235, 907-908
 - DTEXT command 174, 194-197, 194-197
 - ELLIPSE command 219-224, 421-432, 219-224, 421-432
 - FILLET command 237, 237
 - FOLD VIEW command 936-937, 936-937
 - HATCH command 399-373, 369-373
 - HIDE command 984-987, 984-987
 - INTERSECT SURFACE command 297, 983, 983-984
 - LINE command 233-235, 907-908, 233-235, 907-908
 - LIST command 560
 - MEASURE command 561
 - MEASURE ANGLE command 561, 907-908, 907-908
 - MEASURE DISTANCE command 561, 907-908, 907-908
 - MIRROR command 323-324, 324
 - OBJECT SNAP command (OSNAP) 227, 227
 - OFFSET command 907-908, 907-908
 - OSNAP command 227, 227
 - PAN command 984-987, 984-987
 - POLYGON command 210, 238, 210, 238
 - ROTATE command (see *ARRAY command*) 959-960, 959-961
 - ROTATE3D command 959-960, 959-961
 - SETVAR command 565
 - SKETCH command 276-277, 276-277
 - SOLBOX command 984-987, 984-987

- SOLCONE 984–987, 984–987
 SOLCYL command 984–987, 984–987
 SOLMESH command 984–987, 984–987
 SOLSPHERE command 984–987, 984–987
 SOLSUB command 983–987, 983–987
 SOLUNION command 983–987, 983–987
 SOLWEDGE command 983–987, 983–987
 STYLE command 194–197, 194–197
 TEXT command 174, 194–197, 194–197
 VPOINT command 984–987, 984–987
 VIEWPORTS command 324–325, 324–325
 ZOOM command 566–567, 984–987, 566–567, 984–987
 ZOOM WINDOW command 566–567, 984–987, 566–567, 984–987
- COM (computer output microfilm) 131, 831, 838, 131, 831, 839
 Compass 146–148, 163–164, 146–148, 163–164
 beam 146–147, 163–164, 146–147, 163–164
 bow 146–147, 163–164, 146–147, 163–164
 drop 146–147, 163–164, 146–147, 163–164
 inking 146–148, 163–166, 146–148, 163–166
 leads 146–147, 163–164, 146–147, 163–164
 sharpening 146–148, 146–148, 163–164
 Compass leads 146–148, 163–164, 146–148, 163–164
 Computer-aided design (CAD) (see CAD)
 Computer-aided engineering (CAE) (see CAE)
 Computer-aided manufacturing (CAM) (see also CAM) 80, 98, 98, 124–128, 478–513, 478–513
 Computer integrated manufacturing (CIM) (see also CIM) 13, 80, 81, 87, 499, 13, 87, 499
 Computer numerical control (CNC) (see also CNC) 13–14, 81, 99–100, 100, 124–128, 478–513, 13–14, 81, 99–100, 124–128, 478–513
 Computer output microfilm (COM) (see also *Aperture card*) 131, 831, 838, 131, 831, 839
 Computers 13, 840–851, 13, 840–851
 Computers in manufacturing 13, 100, 124–128, 478–513, 840–851, 13, 100, 124–128, 478–513, 840–851
 Concurrent engineering 100, 124–128, 478–513, 840–851, 13, 100, 124–128, 478–513, 840–851
 Cone developments 972–974, 978–979, 972–974, 978–979, 981
 Cones 219–224, 972–974, 219–224, 972–974
 Conics 219–224, 972–974, 219–224, 972–974
- Constructive solid geometry (CSG) 980, 980
 Conventions 308
 Coordinate measuring machine (CMM) 480–513, 480–513
 Coordinates 546–547, 546–547
 Counterbore 321–322, 536–537, 321–322, 536–537
 Counterdrill 321–322, 536–537, 321–322, 536–537
 Countersink 321–322, 536–537, 321–322, 536–537
 Crosshatching (see *Section lining*) 342–373, 343–373
 Computer-aided manufacturing (see CAM) 80, 98, 478–513, 98, 478–513
 CNC (computer numerical control) 13–14, 81, 99–100, 505–513, 13–14, 81, 99–100, 505–513
 CPU (central processing unit) 83, 83
 Cursor 80–87
 Cursor button 80–87
 Curved surfaces 307, 317–319, 530–537, 307, 317–319, 530–537
 Cutter path 505–513, 505–513
 Cutting plane 343–346, 350–351, 967–969, 343–346, 350–351, 967–969
 Cutting plane line 343–346, 350–351, 967–969, 343–346, 350–351, 967–969
 Cylinder developments 203, 971–972, 976–977, 999, 1009–1011, 203, 971–972, 976–977, 1000, 1009–1011
 Cylinders 203, 971–972, 976–977, 203, 971–972, 976–977
- Datum 517, 551–552
 Decimal scale 518–519, 518–519
 Descriptive geometry 9, 880–908, 916–937, 944–961, 9, 880–908, 916–937, 945–961
 CAD 9, 80, 904–908, 935–936, 9, 904–908, 935–936
 fold line 286–289
 lines 880–908, 946–953, 880–908, 946–953
 angle between 901–904, 901–904
 azimuth 889–890, 889–890
 bearing 888–889, 888–889
 foreshortened 316, 886–887, 316, 886–887
 grade 890–893, 890–893
 inclined 316, 886–887, 316, 886–887
 intersecting 319, 894–895, 319, 894–895
 level 890–893, 890–893
 mining applications 883, 883
 multiview projection 885–886, 885–886
 nonintersecting 886–887, 895, 886–887, 895
 oblique 317–318, 317–318
 parallelism 895–896, 895–896
 perpendicular 896–897, 896–897
 point view 883–884, 888, 897, 883–884, 888, 897
- principal 289, 886–887, 289, 886–887
 frontal 289, 886–887, 289, 886–887
 horizontal 289, 886–887, 289, 886–887
 profile 289, 886–887, 289, 886–887
 projection 289, 886–887, 289, 886–887
 shortest distance between 897–899, 901, 887–889, 901
 slope 890–893, 890–893
 true length 313–316, 887–888, 313–316, 887–888
 vertical 287
 visibility 894, 894
- notation key 882, 882
 planes 916–937, 952–955, 916–937, 952–955
 angle between (dihedral angle) 932, 933
 cutting plane 932, 967–969, 967–969
 edge view 317, 919–920, 952, 967–969, 317, 922, 952–953, 967–969
 inclined 918, 920
 oblique 317–318, 317–318, 918–920, 920, 922
 parallelism 926–927, 926–927
 perpendicularity 926–927, 926–927
 piercing points 927–928, 932–935, 927–928, 932–935
 principal 289, 917, 918
 frontal 289, 917, 918
 horizontal 289, 917, 918
 profile 289, 918, 918
 representation 916–917, 916–917
 shortest distance between 924–926, 924–926
 slope 921–924, 921–924
 strike 921–924, 921–924
 true length lines on 918–920, 919–920, 922
 true size (shape) 309–316, 309–316, 918, 922, 952–953, 922–923, 952–953
 vertical 287, 918, 919
 points 880–908, 944–946, 880–908, 944–946
 revolution (rotation) 944–960, 945–961
 edge view using 317, 952, 317, 952–953
 lines 946–951, 946–951
 cone locus 951–952, 951–952
 planes 952–955, 952–955
 true size using 309–316, 952–953, 309–316, 952–953
 point 201, 883–884, 944–946, 201, 883–884, 944–946

- Descriptive geometry *continued*
 - revolution (rotation) *continued*
 - solid 958, 959
 - CAD 7, 14, 80–82, 92–93, 450–463, 956, 958–960, 7, 14, 93, 450–463, 956–957, 959–961
- Design 3D (see also *Pro E and Parametric design*) 7, 14, 19–27, 32–79, 80, 103–128, 450–463, 813–850, 7–8, 14, 19–27, 32–79, 103–128, 450–463, 814, 851
- Design considerations 8, 23, 32–79, 8, 32–79
 - appearance 23–24, 23–24
 - constraints 23, 23
 - costs 23, 23
 - environment 24, 24
 - function 23, 23
 - interchange ability 23, 23
 - maintenance 23–25, 23–25
 - materials 23, 23
 - product life 23–25, 23–25
 - reliability 23–25, 23–25
 - safety 23–25, 23–25
 - standardization 23, 23
- Design engineering 17–23, 103–128, 812–850, 17–23, 103–128, 811–851
- Design for manufacturability (see DFM) 17, 32, 81, 95–96, 480–513, 81, 96, 480–513
- Design models 5, 13, 17–21, 5, 13, 18–21
- Design process 7–9, 17–21, 32–79, 812–850, 7, 17–21, 32–79, 812–851
 - analysis 17, 45–50, 56–58, 45–50, 56–58
 - creative solutions 39–40, 39–40
 - design choice (decision) 50–52, 50–52
 - development 52–59, 10, 52–59
 - evaluation 40–45, 40–45
 - marketing and sales 59–66, 59–66
 - overview 34–36, 34–36
 - problem identification 37–39, 37–39
 - production 59–66, 812–851, 659–666, 812–851
 - project examples 66–73, 1070–1085, 66–73, 1070–1085
 - summary 74–79, 74–79
- Design project 1070–1085, 1070–1085
- Design sketches 33–77, 33–77
- Design supervisor 3–4, 3–4
- Design testing 40–45, 40–45
- Designer, junior 3–4, 4
- Designer, layout 3–4, 4
- Designer, senior 3–4, 4
- Designer 3, 4
- Designing 3, 4
- Detail drawings 519, 810–850, 811–851
 - checklist 568–570, 830–831, 568–570
 - revisions 829–830, 829–830
- Detailer 3–4, 4
- Developments 998–1023, 999–1023
 - bend allowance 1001, 1001
 - bend line 1001, 1001
 - blank 1002, 1002
 - CAD 1003, 1022–1023, 1004, 1022–1023
 - cones 219–224, 972–974, 999, 1011–1013, 219–224, 972–974, 999, 1011–1013
 - curved surfaces 307, 317–319, 530–537, 1008–1013, 307, 317–319, 530–537, 1008–1013
 - cylinders 203, 971–972, 976–977, 999, 1009–1011, 203, 971–972, 976–977, 1000, 1009–1011
 - flat patterns 1003–1004, 1022–1023, 1003–1004, 1022–1023
 - lap 1001, 1001
 - models 1000–1023, 1001–1023
 - nesting 1003–1004, 1003–1004
 - packaging 998, 1005, 1005
 - pattern 998, 1003–1004, 1003–1004
 - prisms 203, 975–976, 999, 1005–1006, 203, 975–976, 1000, 1005–1006
 - pyramids 999, 1006–1008, 1000, 1006–1008
 - seam 1001–1002, 1001–1002
 - sheet-metal 1001–1004, 1001–1004
 - single-curved surfaces 1009, 1009
 - spheres 974–975, 1020–1022, 974–975, 1020–1022
 - tab 1001, 1001
 - transition pieces 1014–1015, 1018, 1014–1015
 - triangulation 1014–1015, 1018–1020, 1014–1015, 1018–1020
 - true length diagram 1006, 1013, 1013–1014
 - types 1000
- DFM (see also *Design for manufacturability*) 17, 32, 81, 95, 96, 480–513, 81, 96, 480–513
- Diameter 532–537, 532–537
- Diazo process 131–132, 831, 131–132, 831
- Dies (see also *Manufacturing processes*) 484, 840–851, 840–851
- Dihedral angle 932, 933
- Digitizer plotter 83, 86, 90–91, 90–91
- Digitizing 83
- Digitizing table 86, 87
- Digitizing tablet 86, 87
- DIMENSION command 174, 563, 563
- Dimensioning 515–570, 516–569
 - ANSI Y14.5 14–15, 515–570, 516–569
 - angles 532–537, 532–537
 - arcs 532–537, 532–537
 - CAD 556–570, 556–570
 - arrowhead variations 561, 561
 - associativity 566–567, 566–567
 - color 563, 984–987, 563, 984–987
 - DIMENSION ANGLE command 567–568, 567–568
 - DIMENSION command 174, 563, 563
 - labels 563, 563
 - layers 562, 562
 - line types 562–564, 562–564
 - menu 87–89, 563, 88–89, 564
 - SETVAR command 565,
 - STYLE command 194–197, 194–197
- ZOOM command 566–567, 984–987, 566–567, 984–987
- ZOOM WINDOW command 566–567, 984–987, 566–567, 984–987
- checklist 568–570, 830–831, 568–570
- datum line 517, 551–552
- datums 551–552
- diameters 532–537, 532–537
 - dual 532–537, 532–537
 - center drill 542, 542
 - chamfers 540–541, 540–541
 - chords 532–537, 532–537
 - fillets and rounds 322, 447–463, 493–495, 322, 447–463, 493–495
 - feature based 556–560, 556–560
 - geometric shapes 543–546, 543–546
 - hole charts 552–555, 552–555
 - hole patterns 552–555, 552–555
 - holes 320–322, 536–537, 546–556, 320–322, 536–537, 546–556
 - counterbore 321–322, 536–537, 321–322, 536–537
 - counterdrill 321–322, 536–537, 321–322, 536–537
 - countersink 321–322, 536–537, 321–322, 536–537
 - spotface 321–322, 536–537, 321–322, 536–537
- keys and keyseats 542, 682–687, 542, 683–687
- knurling 485–489, 542–543, 485–489, 542–543
- machined surfaces 485–489, 485–489
- finish marks 545, 546
- mating 545, 546
- metric standard 517–519, 532, 518–519
- offset 547, 907–908, 548, 907–908
- outlines 534–537, 534–537
- over dimensioning 532–537, 532–537
- not-to-scale (NTS) 519, 529, 530
- polar coordinate 551–552, 552
- radii (arcs) 532–537, 532–537
- rectangular coordinate 546–547, 550–556, 546–547, 550–556
- reference 555, 555
- repetitive features 537–540, 537–540
- rounding off 519
- rounded ends 532–537, 532–537
- sheet tolerance 515
- symbols 85, 537–540, 537–540
- symmetrical outlines 532–537, 532–537
- tabular 552–555, 552–555

- terms 517
 - actual size 517
 - datum 517, 551–552
 - datum feature 517
 - dimension 517
 - feature 517
 - limits of size 517
 - tolerance 515–517
- threads 647–662, 647–662
- tolerances
 - form 551–552
- types 517–519, 517–519
 - decimal-inch 518–519, 518–519
 - dual 519, 519
 - fraction 518–519, 518–519
 - metric 517–519, 518–519
- units 517, 565
 - angular 517, 526–528, 526–528
 - decimal 517–519, 518–519
- Dimensions 520–531, 521–531
 - angular 526–528, 526–528
 - arrowheads 524, 561, 524, 561
 - centerlines, using 305, 307, 305, 307
 - chain line 617, 618
 - coordinate 546–547, 546–547
 - decimal inch 518–519, 518–519
 - diameter 534–537, 534–537
 - hole depths 536–537, 536–537
 - dimension lines 150–155, 520–521, 151–154, 520–521
 - dimetric axes 421–432, 421–432
 - dimetric projection 421–432, 421–432
 - extension lines 150–155, 521–523, 151–154, 521–523
 - finish marks 545, 546
 - grouping 524, 524
 - horizontal 524–525, 524–525
 - leaders 528–529, 528–529
 - lettering 174–197, 525–526, 174–197, 525–526
 - aligned 525–526, 525–526
 - unidirectional 525–526, 525–526
 - limited length and area 529–530, 529–530
 - location 544–547, 544–547
 - millimeter 517–519, 532, 518–519
 - notes (local) 528–529, 547–550, 824–830, 528–529, 547–550, 824–830
 - fillets and rounds 322, 447–463, 493–495, 322, 447–463, 493–495
 - holes 536–537, 546–556, 536–537, 546–556
 - oblique 317–318, 317–318
 - offset 547, 907–908, 548, 907–908
 - pictorials 812–851, 812–851
 - size 544–547, 544–547
 - staggered 524, 524
 - spacing 294
 - symbols 537–540, 537–540
 - vertical 287, 525, 525
- Disk drives 84, 84
- Display devices 80–85, 80–85
- Display menu 87–89, 88–89
- Dividers 161–163, 161–163
 - proportional 161–163, 161–163
 - using 161–163, 304, 161–163, 304
- DOD (Department of Defense) 14–15, 95
- Drafter 3–4, 4
 - junior 3–4, 4
 - senior 3–4, 4
- Drafting 5, 5
 - brushes 134–136, 136
 - checklist 568–570, 830–831, 568–570
 - cleaning pad 136, 165, 136
 - conventions 308
 - equipment 130
 - instruments 130–136, 146–149, 159–166, 131–136, 146–149, 159–166
 - manual 5, 159–166, 5, 159–166
 - materials 130
 - pencils 134–136, 134–136
 - sheets 824, 825–828
 - tapes 134–136
 - techniques 130–136
 - tools 130–136, 131–136
- Drafting machine 131–132, 131–132
 - arm 131–132, 131–132
 - track 131–132, 131–132
- Drafting table 131–132, 131–132
 - light 131–132, 131–132
- Drafting tools 134
 - irregular curves 146, 164–165, 146, 164–165
 - protractor 144, 144
 - triangles 144–145, 201–202, 208, 144–145, 201–202, 208
- Drafting trainee 3–4, 4
- DRAW LINE command 233–235, 907–908, 233–235, 907–908
- Drawing format 149–150, 149–150
- Drawing lines 150–155, 151–154
 - curved 150–155, 159–161, 151–154, 159–161
 - horizontal 150–155, 159–161 151–154, 159–161
 - sloping 150–155, 159–161, 151–154, 159–161
 - vertical 150–155, 159–161, 287, 151–154, 159–161
- Drawing scale 138–143, 519, 138–143
- Drawing sheets 149–150, 824, 149–150, 825–828
- Drawings 810–850, 811–851
 - assembly 7, 810–851, 7, 811–851
 - design 7, 32–79, 812–813, 7, 32–79, 812–813
 - detail 7, 519, 811–851, 7, 812–851
 - engineering 6–7, 810–850, 7, 812–851
 - layout 6–7, 812–850, 7, 813–851
 - mechanical 6–7, 10–11, 18, 818–833, 11, 18–19, 818–833
 - plotting 90–95, 831, 90–95, 831
 - production 7, 812–833, 812–833
 - revisions 829–830, 829–830
- Drillings, keeping clean 165
- Drawing tools (see *drafting tools*)
- Drill bit 483–484, 483–484
- Drill jig 483–484, 483–484
- Drilling 483–484, 483–484
- Drum plotter 90, 90
- Dry cleaning pad 136, 165, 136
- DTEXT command 174, 194–197, 194–197
- ECM (electrochemical machining) 499
- edge view of surface 317, 967–969, 317, 967–969
- EDM (electrical discharge machining) 499
- Electrical engineering 10–12, 11–12
- Electronic design 10–12, 93, 11–12, 93
- Electronic drafting 10–12, 93, 11–12, 93
 - abbreviations Appendix B
 - ANSI standards 14–15, 95, 522–523, 578–635, 522–523, 578–635
 - IC (integrated circuits) 10–12, 11–12
 - lines 150–155, 151–154
 - menu 87–89, 88–89
 - PCB (printed circuit boards) 93, 93
 - assembly drawing 812–850, 811–851
 - plotting 90–95, 831, 90–95, 831
 - terminal areas 82
 - silicon chips 10–12, 11–12
 - symbols 85, 537–540, 537–540
 - templates 145–146, 145–146
- Electronic engineer 93, 93
- Electronic pen 87, 89, 89
- Electrostatic plotter 90–91, 90–91
- Elevators 718, 718
- Ellipses 219–224, 219–224
- ELLIPSE command 238, 238
- Engineer 3–4, 4
 - Engineer, chief 3–4, 4
 - Engineering design 7, 308, 7, 308
 - Engineering office 3–4, 81, 81
 - Engineer, registered 4
 - Engineering graphics 2, 2–1031, 3–1031
 - English units (see *US Customary Units*)
 - Enlarged views 309, 309
 - Erasers 136–138, 136–138
 - Erasing 136–138, 136–138
 - Erasing machine 136–138, 136–138
 - Erasing shield 136–138, 136–138
 - Evinrude 303, 303
 - Exploded assemblies (pictorial) 812–851, 813–851
- Extruding 495–496, 496
- Fabrication drawings 812–851, 812–851
- Facing 485–489, 485–489
- Fasteners 662–689, 662–689
 - CAD 674–677, 687–689, 674–677, 688–690
 - bolts 664–666, 664–666
 - collars 682, 684
 - keys and keyseats 542, 682–687, 542, 683–687
 - nuts 670–671, 670–671
 - pins (machine) 673, 678–680, 678–680
 - clevis 679–680, 680
 - cotter 679–680, 680
 - dowel 679, 680

- Fasteners *continued*
 pins (machine) *continued*
 grooved 679, 680
 spring 678–679, 679
 straight 678, 678
 tapered 678, 678
 representation 671, 671
 retaining rings 682–683, 683
 rivets 680–682, 681–682
 screws 666–670, 666–670
 cap 667–669, 667–669
 machine 666–667, 666–667
 set 669–670, 669–670
 selection of 646, 662
 studs 662–664, 663–664
 washers 671–673, 671–673
- Filletts 322, 447–463, 493–495, 322, 447–463, 493–495
 pictorial 322, 447–463, 493–495, 322, 447–463, 493–495
- FILLET command 237, 237
- Finite element analysis (FEA) 17, 97–98, 1049–1051, 97–98, 1049–1051
- Finite element modeling (FEM) 17, 56–58, 97–98, 1049–1051, 56–58, 97–98, 1049–1051
- First-angle projection 290–292
- Fixtures 286, 505–513, 840–851, 505–513, 840–851
- Flat patterns (see *Development*)
- Flatbed plotters 90–91, 90–91
- Flexible curve 146, 164–165, 146, 164–165
- Flexible manufacturing systems 82, 82
- Floppy disk drives 85, 85
- Floppy disks 85–86, 85–86
- Fluid power 760–775, 760–775
 actuators 773–774, 773–774
 components 763–767, 763–767
 cylinders 763–767, 763–767
 diagrams 774–775, 775
 fluid properties 767, 769–770, 769–770
 hydraulics 760, 763–767, 763–767
 mechanical advantage 762
 pneumatics 760, 763–767, 763–767
 pumps 771–772, 771–772
 reservoir 762, 770, 762
 symbols 761, 763–767, 763–767
 systems 763–767, 763–767
 terms 761–762, 761–762
 valves 764–767, 772–773, 764–767, 772–773
- FOLD VIEW command 936–937, 936–937
- Forging 496, 496
- French curve (see also *Irregular curve*) 146, 164–165, 146, 164–165
- Frontal auxiliary view 9, 387–405, 9, 387–405
- FSCM (Federal Supply Code for Manufacturer's) 820–824, 820–824
- Full sections 353, 354–355
- Function box 86, 86
- Function keys 86, 86
- GD&T (see *Tolerancing*)
- Gears 711–738, 712–720
 backlash 720, 720
 blanks 713, 713
 CAD 733–735, 733–735
 diametrical pitch 717–721, 717–721
 dimensioning 515–570, 722–725, 516–569, 722–725
 pinion 711, 722, 722
 rack 711, 722, 722
 representation (drawing) 722–725, 723–725
 serrations 713
 shaft angle 713
 specifications 715–725
 spline 713, 722, 722
 teeth 712–713, 712–713
 formulas 717, 719–720, 731, 719–720, 731
 helix angle 720–721, 721
 involute 717
 line of action (pressure line) 712–713, 713
 outlines 720, 720
 pressure angle 712–713, 718, 713
 thickness 720, 720
 terms 713, 717, 730–731,
 types 713–721, 713–721
 bevel (miter) 713, 725, 730–732, 730–732
 helical 713, 720–721, 720–721
 internal (ring gear) 713–715, 713–715
 miter (see *Bevel*) 713, 725, 730–732, 730–732
 spur 713–720, 729, 713–720, 729
 worm 713, 732–734, 732–734
- Geometric constructions 200–239, 200–239
 bisectors 207, 207
 angle 207, 207
 line 207, 207
 CAD 226–239, 226–239
 arcs 237, 532–537, 237, 532–537
 circles 263–267, 421–432, 263–267, 421–432
 ellipses 219–224, 421–432, 219–224, 421–432
 lines 226–239, 226–239
 polygons 201–202, 212–213, 201–202, 212–213
 points 233, 233
 circles 207–208, 207–208
 conics 219–224, 972–974, 219–224, 972–974
 dividing a line 206–207, 206–207
 parallel line method 206–207, 206–207
 vertical line method 206–207, 206–207
 ellipse 219–224, 219–224
 fillets 322, 447–463, 493–495, 322, 447–463, 493–495
 helix 200, 224–226, 200, 224–226
 hexagon 211, 211
 hyperbola 219–224, 972–974, 219–224, 972–974
 octagon 211–212, 211–212
 ogee curve 218–219, 218–219
 parabola 219–224, 972–974, 219–224, 972–974
 parallel lines 201, 203, 308, 201, 203, 308
 pentagon 202, 211, 202, 211
 perpendicular lines 201, 203, 201, 203
 polygons 201–202, 212–213, 201–202, 212–213
 rectifying 218–219, 218–219
 spiral of Archimedes 224–225, 224–225
 squares 210–211, 210–211
 tangencies 213–218, 213–218
 triangles 201–202, 208, 201–202, 208
 Geometric dimensioning and tolerancing (GD&T) (see also *Tolerancing*) 576–635, 577–635
- Geometric forms 201–239, 201–239
 angles 202–203, 202–203
 circles 207–208, 207–208
 curved surfaces 307, 317–318, 530–537, 307, 317–318, 530–537
 cylinders 203, 971–972, 976–977, 203, 971–972, 976–977
 helix 200, 224–226, 200, 224–226
 lines 201–203, 201–203
 parallel 201–203, 201–203
 perpendicular 201–203, 201–203
 points 201, 233, 233
 polygons 201–202, 212–213, 201–202, 212–213
 CAD 226–239, 226–239
 regular polygons 201–202, 212–213, 201–202, 212–213
 quadrilaterals 201–202, 201–202
 triangles 201–202, 208, 201–202, 208
 prisms 203, 975–976, 203, 975–976
 pyramids 999, 1006–1008, 1000, 1006–1008
 regular solids 204–206, 204–206
- Glass box theory 287–294, 287–294
- Glossaries See Appendix A
- Graphics tablets 86
- Gravity probe B 27–31, 27–31, 286
- Grids 263–267, 421–432, 263–267, 421–432
- Grinding 488–489, 488–489
- Gyrocompass 947, 947
- Half sections 353, 355
- Hard copy 82
- Hardware 82–83, 83
- Hatch patterns (see *Section lining*) 342–373, 343–373
- Heat treatment 499, 499
 annealing 499, 499
 hardening 499, 499
 normalizing 499, 499
 punching 497–499, 498–499
 quenching 499, 499
 tempering 499, 499
- Helicoids 224–226, 224–226
- Helix 200, 224–226, 200, 224–226
- Hexagon 211, 211
- Hidden lines 150–155, 306–307, 151–154, 306–307

- HIDE command 984–987, 984–987
- Hole representation 320–322, 536–537, 320–322, 536–537
- counterbore 321–322, 536–537, 321–322, 536–537
 - counterdrill 321–322, 536–537, 321–322, 536–537
 - countersink 321–322, 536–537, 321–322, 536–537
 - spotface 321–322
- HVAC 966
- Hyperbola 219–224, 972–974, 219–224, 972–974
- IC (integrated circuit) 10–12, 11–12
- Image planes 288–294, 288–294
- Industrial designer 3–4, 21, 21
- Input devices 84–86, 84–86
- Instruments 130–131, 146–149, 131, 146–149
- compass 146–148, 163–164, 146–148, 163–164
 - dividers 161–163, 304, 161–163, 304
 - inking 146–148, 165–166, 146–148, 165–166
- Instrument drawings 159–166, 159–166
- Intersecting surfaces 319, 966–991, 366, 967–991
- Intersections 966–991, 967–991
- CAD 980, 983–991, 980, 983–991
 - cone and cylinder 972–974, 978–979, 972–974, 978–979, 981
 - cone and prism 972–974, 982, 972–974, 982
 - cone and sphere 972–974, 972–974
 - cones 219–224, 972–974, 219–224, 972–974
 - conic sections 219–224, 972–974, 219–224, 972–974
 - ellipse 219–224, 972–974, 219–224, 972–974
 - hyperbola 219–224, 972–974, 219–224, 972–974
 - parabola 219–224, 972–974, 219–224, 972–974
- cylinder and prism 971–972, 971–972
- cylinders 203, 971–972, 976–977, 203, 971–972, 976–977
- line of intersection 966
- plane and plane 967–969, 967–969
 - plane and cylinder 969–970, 969–970
 - plane and prism 969–970, 969–970
 - plane and sphere 974–975, 974–975
 - prism and cylinder 975–976, 975–976
 - prisms 203, 975–976, 203, 975–976
 - sphere and cylinders 974–975, 982, 974–975, 982
- Irregular curve 146, 164–165, 146, 164–165
- ISO (International Standards Organization) 95, 292, 292
- ISO drawing 95
- Isometric drawing 421–432, 421–432
- angles 263–267, 313, 421–432, 532–537, 263–267, 313, 421–432, 532–537
 - arcs 532–537, 532–537
 - arrowheads 524, 561, 524, 561
 - axes 421–432, 421–432
 - box method 286–305, 286–305
 - centerlines 150–155, 305, 307, 151–154
 - circles 207–208, 207–208
 - dimensioning 305, 305
 - ellipses 219–224, 219–224
 - grids 263–267, 421–432, 263–267, 421–432
 - hidden lines 150–155, 306–307, 151–154, 306–307
 - isometric lines 421–432, 421–432
 - nonisometric lines 263–267, 421–432, 263–267, 421–432
 - offset dimensions 547, 548
- Isometric projection 421–432, 421–432
- Jigs 17, 286, 840–851, 840–851
- JIS (Japanese Industrial Standards) 14–15, 95
- JIT (just-in-time) 80–81, 81
- Joystick 88–90, 88–90
- Keyboards 86, 86
- Keyboard entry 86
- Keys, keyseats, and keyways 542, 682–687, 542, 683–687
- dimensioning 542, 682–687, 542, 683–687
 - design 682–687, 683–687
- Knurling 485–489, 542–543, 485–489, 542–543
- Landscape architecture 10–11, 93–94, 11, 93–94
- Laser plotter 90–91, 90–91
- Laser printer 90, 90
- Lathe 485–489, 485–489
- Layout designer 3–4, 7, 4, 7
- Layout drawings 3, 812–850, 812–851
- Lead 134–136, 134–136
- compass 146–147, 163–164, 146–147, 163–164
 - plastic 146–147, 146–147
- Leroy set 189–191, 188–191
- Lettering 174–197, 174–197
- aids 175–185, 176–189
 - alphabet 174–197, 174–197
 - ANSI 14–15, 95, 176–186, 176–186
 - appliqués 188–191, 188–191
 - CAD 191–197, 191–197
 - DTEXT command 174, 194–197, 194–197
 - STYLE command 194–197, 194–197
 - TEXT command 174, 194–197, 194–197
- text fonts 174, 194–197, 194–197
- text justification 194–197, 194–197
- text menu 88–89, 194–197, 88–89, 194–197
- text variations 194–197, 194–197
- composition 174–197, 175–195
- extended 194–197, 194–197
- form 174–186, 174–186
- fractions 185–186, 185–186
- frechand 174–186, 174–186
- Gothic alphabet 176–186, 190, 176–186, 190
- guide 176–186, 176–186
- guidelines 176–186, 176–186
- heights 176–186, 176–186
- inclined 175–197, 316, 175–197, 316
- justification 194–197, 194–197
- Leroy 188–191, 188–191
- lowercase 176–185, 176–185
- manual 174–188, 175–188
- methods 174–197, 175–197
- notes 187–188, 528–529, 547–550, 824–830, 187–188, 528–529, 547–550, 824–830
- parts list 187–188, 820–824, 187–188, 820–824
- phototypeset 188–190, 188–190
- preprinted 188–190, 188–190
- printed 188–190, 188–190
- spacing 179–185, 179–185
- standard 178–185, 178–185
- stroke sequence 178–185, 178–185
- styles 194–197, 194–197
- templates 189–191, 189–191
- transfer 189–191, 189–191
- uniformity 178–185, 178–185
- uppercase 175–185, 175–185
- vertical 175–187, 175–187
- Library 89
- parts 89, 89
 - symbols 85, 537–540, 537–540
- Light pen 87, 89, 89
- Light table 131–132, 131
- Limits and fits (see also *Tolerancing*) 620–635, 620–635
- calculating 620–621, 628–633, 620–621, 628–633
 - clearance 620–621, 620–621
 - force 627, 627
 - hole basis system 629–630, 630
 - interference 620–621, 620–621
 - limits 620–621, 620–621
 - locational 543–546, 621, 626, 543–546, 626
 - metric 517–519, 629–631, 518–519, 630–631
 - preferred 621, 627–628, 627–628
 - Renard preferred numbers 620–621, 620–621
 - shrink 627
 - single 620
 - tables 627, 627
 - tolerance zones 627–628
 - transition 620–621, 620–621
- LINE command 233–235, 907–908, 233–235, 907–908

- Line fonts (see text fonts under *Lettering*)
- Line of sight 286–292, 343–346, 286–292, 343–346
- Lines (see also *Drawing lines*)
- CAD 226–239, 226–239
 - heavy 150–155, 151–154
 - medium 150–155, 151–154
 - parallel 150–155, 151–154
 - perpendicular 150–155, 151–154
 - printable 150–155, 151–154
 - thin 150–155, 151–154
- Line thicknesses 150–155, 151–154
- Line types 150–155, 151–154
- ANSI 150–155, 151–154
 - break 150–155, 151–154
 - centerlines 150–155, 305, 307, 151–154, 305, 307
 - construction 150–155, 151–154
 - cutting plane 150–155, 967–969, 151–154, 967–969
 - dimension 150–155, 305, 519–521, 151–154, 305, 519–521
 - extension 150–155, 521–523, 151–154, 521–523
 - hidden 150–155, 151–154
 - leader 150–155, 528–529, 151–154, 528–529
 - phantom 150–155, 151–154
 - section 150–155, 151–154
 - viewing plane 150–155, 151–154
 - visible 150–155, 151–154
- LIST command 560, 905–905, 905–906
- Machining center 485–489, 485–489
- turning 485–489, 485–489
 - vertical 485–487, 485–487
- Machine tool operations (see also *Manufacturing processes* and *CAD/CAM*)
- 80–84, 92–93, 98–100, 110, 478–513, 81, 93, 98–100, 110, 478–513, 811
 - boring 484–489, 484–489
 - broaching 484, 484
 - CNC (see also *Computer-aided manufacturing*) 13–14, 81, 84, 99–100, 485–513, 13–14, 81, 99–100, 485–513
 - drilling 483–484, 483–484
 - counterboring 483–484, 483–484
 - countersinking 483–484, 483–484
 - reaming 483–484, 483–484
 - spotfacing 483–484, 483–484
 - grinding 488–489, 488–489
 - milling 485–489, 485–489
 - end 487–489, 487–489
 - face 487–489, 487–489
 - finishing pass 485–489, 485–489
 - islands 485–489, 485–489
 - plane 485–489, 485–489
 - pocketing and profiling 485–489, 485–489
 - shell 485–489, 485–489
 - planning and shaping 485–489, 485–489
 - sawing 487, 490, 490
 - turning 485–489, 485–489
- Magnetic disk 85–86, 85–86
- Magnetic tape 85–86, 85–86
- Manual drafting 5, 5
- Manufacturability (see also *DFM* and *Dcsign for manufacturability*) 17, 32, 81, 95–96, 480–513, 81, 96, 480–513,
- Manufacturing 17, 478–512, 479–512
- Manufacturing design 10–11, 17, 11
- Manufacturing engineering 10–11, 17, 11
- Manufacturing processes (see also *Machine tool operations* and *CAD/CAM*) 80–84, 92–93, 98–100, 81–84, 93, 98, 478–513, 478–513, 811
- CAD/CAM 4, 10–14, 80–84, 92–93, 98–100, 124–128, 478–513, 11, 13–14, 81–84, 93, 99–100, 124–128, 478–513, 811
 - automated 504–513, 504–513
 - casting (see also *Casting*) 322, 493–495, 322, 493–495
 - extruding 495–496, 496
 - forging 496, 496
 - cold 496, 496
 - drop 496, 496
 - punching 497–499, 498–499
 - blanking 497–499, 498–499
 - cutting 497–499, 498–499
 - perforating 497–499, 498–499
 - piercing 497–499, 498–499
 - shearing 497–499, 498–499
 - stamping 496–498, 496–498
- Mapping 95, 95
- Marine engineering 10–11, 11
- Market analysis 17
- Material specification, section 347–348, 347–348
- Materials (see also *Heat treatment*) 499, 499
- MEASURE command 561
- MEASURE ANGLE command 561, 906–908, 906–908
- MEASURE DISTANCE command 561, 906–908, 906–908
- Measurement, standards 14–16, 516–518, 516–518
- SI 14–15, 516–517, 516
 - US 14–15, 517, 517
- Measuring 561, 906–908, 906–908
- Mechanical design 7, 10–11, 18–19, 32–79, 95–96, 7, 11, 18–19, 32–79, 95–96
- Mechanical engineering 10–11, 18–19, 95–96, 11, 18–19, 95–96
- Mechanical engineer's scale 141–143, 141–142
- Media 93–85
- Menus 87
- Metric drawings 517–519, 518–519
- Metric scale 143, 143
- Metric units 517–519, 532, 518–519
- Microfiche 131–132, 131–132
- Microfilm 131–132, 131–132
- Micrometer 490, 490
- MIL (Military Standards) 14–15, 95
- Milling 485–489, 485–489
- Mills 485–489, 485–489
- Mining engineering 10–11, 11
- MIRROR command 323, 323–324
- Modeling 18–22
- modeling, CAD 4–5, 7, 17–21, 80–82, 92–93, 5, 7, 17–21, 81–82, 93
 - modeling, physical 5, 20–21, 287, 323–325, 5, 20–21, 287, 323–325
- Models 17–21, 18–21
- CAD 3D, 4, 6, 9, 13, 18–21, 80–82, 92–93, 287, 6–8, 13, 18–21, 81, 93, 287
 - mock-up 5, 5
 - presentation 5, 5
 - product 5, 17–18, 5, 18
 - prototype 5, 5
 - systems 20, 20
- Mold design 505–513, 505–513
- Mouse 88, 88
- Multiview drawings, 286–326
- one-view 292, 295, 295
 - multi-view 292–309
 - three-view 287–302, 287–302
 - two-views 292, 296
- Multiview projection 286–326, 286–326
- adjacent views 286–300, 394–395, 286, 299–300, 394–395
 - angles 202–203, 313, 532–537, 202–203, 313, 532–537
 - blocking-out views 296–300, 297–301
 - CAD 7, 9, 80–82, 92–93, 224–239, 287, 295, 7, 81, 93, 224–239, 287, 295
 - drawing order 301, 301
 - glass box theory 287–293, 288, 293
 - auxiliary views 9, 387–405, 9, 387–405
 - fold line 287–289, 287–289
 - normal/natural method 287, 294
 - normal surface 309, 309
 - orthographic projection 286–326, 287–326
 - first-angle 290–292, 291–292
 - image planes 288–294, 288–294
 - line of sight 288–291, 343–346, 288–291, 343–346
 - third-angle 286–309, 287–309
 - precedence of lines 150–155, 151–154
 - projection symbol 292–293, 292–293
 - shape description 481–482, 481–482
 - surfaces and edges in views 311–313, 311–313
 - angle of inclination 316, 316
 - angled surfaces 311–313, 311–313
 - conical surfaces 219–224, 972–974, 219–224, 972–974
 - curved surfaces 307, 317–319, 530–537, 307, 317–319, 530–537
 - cylindrical surfaces 317–319, 317–319
 - edge view of surfaces 313, 317, 967–969, 313, 317, 967–969
 - foreshortened surfaces 316–317, 316–317
 - inclined surfaces 313, 316, 313, 316

- intersecting surfaces 319, 319
- oblique surfaces 317–318, 317–318
- related surfaces and edges 313–319, 313–319
- spherical surfaces 318–318, 317–318
- tangent surfaces 322–323, 322–323
- true shape/size surfaces and areas 306–316, 306–316
- visualizing shapes and surfaces 311–316
- views
 - adjacent 286–300, 394–395, 286, 299–300, 394–395
 - alignment 294–300
 - centerlines 305, 307, 305, 307
 - choice 286–300
 - curved 307, 317–319, 530–537, 307, 317–319, 530–537
 - features 286–307
 - description 286–307
 - divider method 304, 304
 - drafting 5, 5
 - conventions 308
 - enlarged 309, 309
 - hidden lines 306–307, 306–307
 - miter line method 302–304, 320, 302, 304, 320
 - parallel edges 308, 308
 - partial 308, 308
 - projection lines 288–289, 306–307, 289, 306–307
 - radius method 304, 304
 - revolved 309–310, 360, 309–310, 360
 - rotated 309–310, 310
 - scale method 304, 304
 - selection 286–304, 286–304
 - shape description of 309–310, 309–310
 - spacing 294–298
 - visualization 286–313, 286–313
- Network 84
- Networked system 84
- NC (numerical control) (see also CNC)
 - 13–14, 81, 99–100, 504–513, 13–14, 81, 99–100, 505–513
- NC tool paths 505–513, 505–513
- Normal/natural method of projection 287, 294, 306
- Normal surface 309, 309
- Notes 528–529, 547–550, 824–830, 528–529, 547–550, 824–830
 - general 528–529, 547–550, 824–830, 528–529, 547–550, 824–830
 - local 528–529, 547–550, 824–830, 528–529, 547–550, 824–830
- Numerical control (see NC and CNC)
 - 13–14, 81, 99–100, 505–513, 13–14, 81, 99–100, 505–513
- Nuts 670–671, 670–671
- OBJECT SNAP command (see OSNAP)
- Oblique projection 432–435, 432–435
 - axes 432–435, 432–435
 - cabinet 432–435, 432–435
 - cavalier 432–435, 432–435
 - general 432–435, 432–435
 - offset dimensions (measurements) 432–435, 546–547, 432–435, 546–547
- Oblique surfaces 317–318, 317–318
- Octagons 211–212, 211–212
- OFFSET command 907–908, 907–908
- Offset dimensions (measurements) 547, 907–908, 548, 907–908
- Offset sections 547, 907–908, 548, 907–908
- Ogee curves 218–219, 218–219
- One-view drawings 292, 295, 295
- Opposite-hand parts 323, 323
- Orthographic projection (see *Multiview projection*)
- OSNAP command 227, 227
 - CENter 227, 227
 - ENDpoint 227, 227
 - MIDpoint 227, 227
 - INTersection 227, 227
 - TANgent 227, 227
- Outline sections 352–353, 353
- Packaging 1000, 1005, 1016–1018, 1016–1018
- PAN command 984–987, 984–987
- Parabolas 219–224, 972–974, 219–224, 972–974
- Paraboloids 219–224, 219–224
- Parallel lines 201, 203, 308, 201, 203, 308
- Parallel straightedge 132–133, 132–133
- Parametric design 4, 103–128, 156–157, 192–193, 314–316, 450–463, 103–128, 156–157, 192–193, 314–316, 450–463
 - associative 119, 119
 - assemblies 111–113, 832–837, 111–113, 832–837
 - auxiliary views 398–399, 398–399
 - bill of materials 832–837, 832–837
 - blends 702–704, 702–704
 - cams 748–749, 748–749
 - chamfers 228–232, 540–541, 228–232, 540–541
 - child 106, 106
 - constraints 105, 105
 - cross sectional views 363–366, 363–366
 - cut motion 503, 503
 - datum 108–109, 455–457, 517, 551–552, 929–932, 108–109, 455–457, 551–552, 929–932
 - datum axes 900–901, 900–901
 - dimensioning 556–560, 556–560
 - drawing formats 156–157, 156–157
 - drawing views 314–316, 314–316
 - families 114–115, 114–115
 - feature based modeling 104–109, 556–560, 104–109, 556–560
 - finite element analysis 1049–1051, 1049–1051
- gear teeth 726–728, 726–728
- intersecting 988–991, 988–991
- manufacturing 124–128, 500–503, 124–128, 500–503
- notes 192–193, 528–529, 547–550, 824–830, 192–193, 528–529, 547–550, 824–830
- packaging 1016–1018, 1016–1018
- parent-child 111, 111
- parametric dimensions 105, 105
- part families 674–677, 674–677
- patterning 726–728, 726–728
- pictorials 458–463, 458–463
- Pro Manufacturing 500–503, 500–503
- revolving features and parts 956–958, 956–958
- rounds 228–232, 228–232
- sheet metal parts 988–991, 1016–1018, 988–991, 1016–1018
- sketching 105, 114–118, 156–157, 268–272, 105, 114–118, 156–157, 268–272
- standard parts 674–677, 768–769, 674–677, 768–769
- springs 702–704, 702–704
- sweeps 702–704, 702–704
- threads 674–677, 674–677
- tolerancing 622–625, 622–625
- view types 314–316, 314–316
- welding symbols 794, 794
- Part creation/design
- Part profile
- Partial auxiliary views 393–394, 393–394
- Partial views 308, 308
- Parts list 820–824, 820–824
 - description 821–824, 821–824
 - FSCM (Federal Supply Code for Manufacturer's) 820–824, 820–824
 - part number 823–824, 823–824
 - quantity required 823–824, 823–824
- PC CAD 93, 93
- PCB (see also *Printed circuit board*) 93, 93
- Pen plotter 87, 90–91, 90–91
- Pencil 134–136, 134–136
 - cleaning 136, 165, 136
 - fine line 135–136, 135–136
 - lead 134–136, 134–136
 - lead holder 135–136, 135–136
 - mechanical lead holders 135–136, 135–136
 - sharpeners 135–136, 135–136
 - sharpening 134–136, 134–136
 - thin line 134–136, 134–136
 - wood 134–136, 134–136
- Pencil sharpeners/pointers 135–136, 135–136
- Perpendicular lines 150–155, 201, 203, 151–154, 201, 203
- Perspective projection 435–443, 435–443
 - angle of vision 435–443, 435–443
 - cone of rays 435–443, 435–443
 - grids 435–443, 435–443
 - ground line 435–443, 435–443
 - height line 435–443, 435–443
 - horizon line 435–443, 435–443

- Perspective projection *continued*
 one-point (parallel) 435–443, 435–443
 picture plane 435–443, 435–443
 station point 435–443, 435–443
 two-point (angular) 435–443, 435–443
 three-point (oblique) 435–443, 435–443
 vanishing point 435–443, 435–443
- Petrochemical plant design 10–11, 95, 11, 95
- Photoplotter 91, 91
- Physical models 5, 17, 21, 5, 21
- Pictorial drawings 417–463, 418–462
 assemblies 443–460, 812–851, 443–460, 812–851
 axonometric projection 420–433, 420–433
 dimetric 421–432, 421–432
 isometric 421–432, 421–432
 isometric drawing 421–432, 421–432
 trimetric 421–432, 421–432
 break lines 150–155, 444–445, 151–154, 444–445
- CAD generated pictorials 80–82, 447–463, 81, 447–463
 exploded assemblies 447–463, 812–851, 447–463, 812–851
 fillets 447–463, 447–463
 oblique projection 432–435, 432–435
 cabinet 432–435, 432–435
 cavalier 432–435, 432–435
- Perspective projection 435–443, 435–443
 one-point (parallel) 435–443, 435–443
 two-point (angular) 435–443, 435–443
 three-point (oblique) 435–443, 435–443
 rounds 322, 435–443, 322, 435–443
 shading and shadows 435–443, 435–443
 single-plane projections 435–443, 435–443
 technical illustration 6–7, 12, 96–97, 443–460, 6, 12, 96–97, 443–460
 threads 444–447, 444–447
- Pins (see also *Fasteners*) 673, 678–680, 678–680
- Piping design 95–96, 95–96
- Piping fabrication drawings 95–96, 95–96
- Pipe threads 661–662, 661–662
- Planer 490
- Planning 1071–1085, 1071–1085
- Plant design 95, 95
- Plastic lead 146–147, 163–164, 146–147, 163–164
- Plot 90–95, 831, 90–95, 831
- Plotters 90–95, 831, 90–95, 831
 digitizer 83, 86
 drum 90–95, 90–95
 electrostatic 90–95, 831, 90–95
 flat bed 90, 90
 laser 90–95, 90–95
 pen 87, 89–91, 831
 photoplotter 91, 91
- Plotting 90–95, 831, 90–95, 831
- POINT command 880–908, 944–946, 880–908, 944–946
- Pointing devices 88, 88
- Points 233, 233
- POLYGON command 210, 238, 210, 238
- Polygons 201–202, 201–202
- Power plant 95–96, 95–96
- Precedence of lines 150–155, 305, 151–154, 305
- Primary auxiliary views 389–390, 389–390
- Printed circuit board (PCB) 93
 software 82, 92–93, 93
- Printers 91–92, 91–92
 dot matrix 91–92, 91–92
 jet ink 91–92, 91–92
 laserjet 91–92, 91–92
 letter quality 91–92, 91–92
- Prism developments 203, 975–976, 203, 975–976
- Pro Engineer 103–128, 156–157, 314–316, 450–463, 103–128, 156–157, 314–316, 450–463
 assemblies 104, 111–113, 832–837, 104, 111–113, 832–837
 associative 119, 119
 auxiliary views 398–399, 398–399
 bill of materials 832–837, 832–837
 blends 702–704, 702–704
 cams 748–749, 748–749
 chamfers 228–232, 540–541, 228–232, 540–541
 child, 106, 106
 constraints 105, 105
 cross sectional views 363–366, 363–366
 cut motion 503, 503
 datum 108–109, 455–457, 517, 551–552, 929–932, 108–109, 455–457, 551–552, 929–932
 datum axes 900–901, 900–901
 design intent 104, 104
 dimensioning 556–560, 556–560
 drawing formats 156–157, 156–157
 drawing views 314–316, 314–316
 families 113–114, 113–114
 feature based modeling 104–114, 556–560, 104–114, 556–560
 finite element analysis 1049–1051, 1049–1051
 gear teeth 726–728, 728–728
 intersecting 988–991, 988–991
 manufacturing 124–128, 500–503, 124–128, 500–503
 mate 832–837, 832–837
 notes 192–193, 528–529, 547–550, 824–830, 192–193, 528–529, 547–550, 824–830
 offset 832–837, 832–837
 packaging 1016–1018, 1016–1018
 part families 674–677, 674–677
 PCs 120–122, 120–122
 parent-child 111, 111
 parametric dimensions 105, 556–560, 105, 556–560
 patterning 726–728, 726–728
 pictorials 458–463, 458–463
 Pro Manufacturing 500–503, 500–503
 report mode 832–837, 832–837
 revolving features and parts 956–958, 956–958
- rounds 228–232, 228–232
 sketch 105, 114–118, 156–157, 268–272, 105, 114–118, 156–157, 268–272
 sheet metal parts 988–991, 1016–1018, 988–991, 1016–1018
 springs 702–704, 702–704
 standard parts 674–677, 768–769, 674–677, 768–769
 storage 122–123, 122–123
 sweeps 702–704, 702–704
 threads 674–677, 674–677
 tolerancing 622–625, 622–625
 view types 314–316, 314–316
 welding symbols 785–794, 785–794
- Product design 7–10, 17–18, 21–23, 32–79, 96, 7, 18, 21–23, 32–79, 96
 optimization 26, 26
 parameters 22, 22
 tree 27, 27
- Product development 17, 18–27, 480, 18–27, 480
- Product engineering 17–18, 480, 18, 480
- Production 17, 480–513, 812–850, 480–513, 812–851
- Profile auxiliary views 393–393, 393–394
- Programming 505–513, 840–851, 505–513, 840–851
- Project planning 1071–1085, 1071–1085
- Projection lines 288–289, 306, 288–289, 306
- Projection symbol 292–293, 292–293
- Punching 497–499, 498–499
- Pyramid developments 999, 1006–1008, 1000, 1006–1008
- Pyramids 999, 1006–1008, 1000, 1006–1008
- Quality control 504–513, 504–513
- Random access memory (RAM) 83–84, 84
- Rapid prototyping (RP) 56–58, 56–58
- Read only memory (ROM) 83–84, 84
- Reading a drawing 309–310, 309–310
- Rectifying 218–219, 218–219
- Reference plane method 395–397, 395–397
- Removed sections 358–360, 358–360
- Repetitive features 546–555, 546–555
- Reproduction equipment (see also *Plotters*) 132, 134, 831, 132, 134, 831
- Reprographics (see also *COM*) 131–134, 831, 838, 131–134, 831, 839
- Resolution 82–92, 125–132
- Retaining rings 682–683, 683
- Revisions 829–830, 829–830
- Revolved sections 309–310, 360, 309–310, 360
- Revolved views 309–310, 309–310
- Right-hand parts 323, 323
- Rivets 680–682, 681–682
- Robotics 99–100, 511–513, 99–100, 511–513
 library 99–100, 511–513, 511–513
 simulation 99, 100, 511–513, 511–513

- workcell 99–100, 511–513, 99–100, 511–513
 - work envelope 511–513, 511–513
 - Robotics system 17, 99–100, 511–513, 99–100, 511–513
 - Robots 17, 99–100, 511–513, 99–100, 511–513
 - Room boss 3, 4, 4
 - ROTATE command (see *ARRAY command*) 959–960, 959–961
 - Rotated views 309–310, 310
 - Rounds 322, 322
 - pictorial 322, 493–495, 322, 493–495
 - RP (Rapid Prototyping) 56–58, 56–58
 - Runouts 323, 323

 - Sawing 487, 490, 490
 - Scales 138–143, 138–143
 - architect's 140–142, 140–142
 - civil engineer's 139–141, 139–141
 - mechanical engineer's 141–143, 141–142
 - metric 143, 143
 - Scanners 91, 91
 - Screen cursor 80–87
 - Screen menu 87–89, 88–89
 - Screw threads (see *Threads*) 647–662, 647–662
 - Screws (see also *Fasteners*) 662–689, 662–689
 - Secondary auxiliary views 389–390, 394–396, 389–390, 394–396
 - Section lines 150–155, 151–154
 - Sections (sectional views) 342–373, 343–373
 - arrows 342–373, 343–373
 - assemblies 367–368, 367–368
 - breaks 367, 367–368
 - CAD 368–373, 368–373
 - 3D sections 371–373, 371–373
 - CUT PLANE command 371–373, 983–987, 371–373, 983–987
 - HATCH command 369–373, 369–373
 - hatch patterns 369–373, 369–373
 - INTERSECT SURFACE command 297, 983, 983–984
 - conventions 308, 342
 - cutting plane 343–346, 350–351, 967–969, 343–346, 350–351, 967–969
 - cutting plane line 343–346, 350–351, 967–969, 343–346, 350–351, 967–969
 - general-purpose section lines 150–155, 151–154
 - hidden lines in sections 348–349, 348–349
 - identification (see *view identification letters*) 351–352, 351–352
 - intersections in section
 - line of sight (viewing direction) 287–292, 343–346, 288–292, 343–346
 - material specification 347–348, 347–348
 - outline 352–353, 353
 - ribs in section 352–353, 353
 - rotated 309–310, 310
 - section lining 347–349, 347–349
 - section symbols (see *Material specification*)
 - shafts in section 356–358, 356–358
 - spokes in section 357, 357
 - thin 352–353, 353
 - types 353–362, 353–362
 - aligned 354
 - assembly 7, 812–850, 812–851
 - auxiliary view 9, 387–405, 9, 387–405
 - broken-out 357–360, 357–360
 - full 353, 354–355
 - half 353, 355
 - offset 353–354
 - removed 358–360, 358–360
 - revolved 309–310, 360, 309–310, 360
 - view identification letters 351–352, 351–352
 - Set screw (see *Fasteners*)
 - SETVAR command 565
 - Sheet metal 988–991, 1016–1018, 988–991, 1016–1018
 - Shafts 711–738, 712–738
 - Shape description 481–482, 481–482
 - Shaper 490
 - Sharpener 135–136, 135–136
 - Silicon chips (see also *IC*) 10–11, 12
 - Sketching 250–277, 250–277
 - angles 257–258, 257–258
 - arcs 257–258, 257–258
 - CAD 276–277, 276–277
 - SKETCH command 276–277, 276–277
 - circles 207–208, 207–208
 - curves 257–258, 257–258
 - grids 253, 435–443, 435–443
 - line types 150–155, 251–255, 151–154, 251–255
 - lines 150–155, 251–255, 151–154, 251–255
 - materials 250–252, 250–252
 - projection methods 258–269, 258–269
 - isometric 263–267, 421–432, 263–267, 421–432
 - angles 263–267, 313, 421–432, 532–537, 263–267, 313, 421–432, 532–537
 - arcs 263–267, 421–432, 263–267, 421–432
 - circles 263–267, 421–432, 263–267, 421–432
 - construction 263–267, 421–432, 263–267, 421–432
 - ellipses 219–224, 421–432, 219–224, 421–432
 - grids 223–267, 421–432, 263–267, 421–432
 - isometric lines 263–267, 421–432, 263–267, 421–432
- nonisometric lines 263–267, 421–432, 263–267, 421–432
- multiview 258–267, 258–267
 - blocking-out views 258–267, 296–300, 258–267, 297–301
 - glass box theory 258–267, 287–294, 258–267, 288–294
 - view alignment 258–267, 293–294, 299, 293, 299, view selection 258–267, 292, 299
- oblique 273–276, 432–435, 273–276, 432–435
 - axes 273–276, 432–435, 273–276, 432–435
 - cabinet 273–276, 432–435, 273–276, 432–435
 - cavalier 273–276, 432–435, 273–276, 432–435
 - third-angle 273–276, 286–292, 273–276
 - perspective 273–276, 435–443, 273–276, 435–443
- Software applications 82, 92
 - aerospace 10–12, 11–12
 - architecture 10–11, 93–94, 11–12, 93–94
 - CAM 80, 98, 124–128, 478–513, 98, 124–128, 478–513
 - civil 10–11, 95, 11, 95
 - electronic (see also *Electronics and PCB*) 10–12, 93, 11–12, 93
 - FEA and FEM 10–11, 56–58, 97–98, 11, 56–58, 97–98
 - landscape architecture 10–11, 93–94, 10–11, 93, 94
 - mapping 95, 95
 - mechanical design 10–11, 18–27, 32–79, 95–96, 11, 18–27, 32–79, 95–96
 - NC and CNC 13–14, 81, 99–100, 505–513, 13–14, 81, 99–100, 505–513
 - pipng (see also *Pipng*) 95–96, 95–96
 - plant design 32–79, 95, 32–79, 95
 - product design 10, 17, 21–27, 96, 21–27, 82, 96, 96
 - robotics 99–100, 511–513, 99–100, 511–513
 - space planning 1071–1085, 1071–1085
 - structural 10–11, 94–95, 11, 94–95
 - technical illustration 6–7, 12, 96, 97, 6, 12, 96–97
- SOLBOX command 984–987, 984–987
- SOLCONE 984–987, 984–987
- SOLCYL command 984–987, 984–987
- SOLMESH command 984–987, 984–987
- SOLSPHERE command 984–987, 984–987
- SOLSUB command 984–987, 984–987
- SOLUNION command 983–987, 983–987
- SOLWEDGE command 984–987, 984–987
- Spheres 974–975, 974–975
- Spindle 487
- Spiral of Archimedes 224–225, 224–225

- Spokes 357, 357
- Spotface 485–489, 485–489
- Springs 695–707, 695–707
 CAD 702–701, 702–704
 compression 696, 698–699, 696, 698–699
 constant force 696, 705
 definitions 696
 drawing 697, 705–706, 697, 705–706
 from tooling libraries 697, 840–851, 840–851
 extension 521–523, 696, 698, 521–523, 696
 flat 696, 701, 701
 garter 696, 699–700
 extension 696
 helical tension 698,
 helical torsion 696, 698, 700, 705
 mechanical 695
 right-hand and left-hand 323, 696, 698, 323, 698
 spiral torsion spring 700, 700
 terms 696
 washers 700–701, 701
- Standards 14–15, 578–635, 578–635
 ANSI 14–15, 95, 578–635, 578–635
 company 14–15
 DOD 14–15, 95
 ISO 14–15, 95, 292, 578–635, 292, 578–635
 MIL 14–15, 95
- Stereolithography 56–58, 1079–1085, 56–58, 1079–1085
- Stock list (see *Parts list* and *Bill of materials*)
 820–824, 820–824
- Stock, material 481–482, 481–482
 bar 481–482, 481–482
 piece 481–482, 481–482
 shapes 481–482, 481–482
- Straightedge 132–133, 132–133
- Storage equipment 130–131
- Structural engineering 10–11, 94–95, 11, 94–95
- Structural shapes 10–11, 94–95, 481–482, 11, 94–95, 481–482
- Studs 662–664, 663–664
- STYLE command 194–197, 194–197
- Successive auxiliary views 400–402, 400–402
- Surface texture specification 490–494, 490–495
 flaws 490–493, 490–493
 roughness 490–493, 490–493
 roughness height 490–493, 490–493
 roughness width 490–493, 490–493
 smoothness 490–493, 490–493
 symbols 490–493, 490–493
 texture 490–495, 490–495
 waviness 490–493, 490–493
 waviness width 490–493, 490–493
- Surfaces (see *Multiview projection*)
- Symbols 85, 537–540, 537–540
- Système International (SI) 14–15, 516–517, 516
- Systems design 20–21, 20–21
- Tablet menu (see *Menu*) 80–88, 88–89
- Tangencies 213–218, 213–218
- Tangent arcs 213–218, 213–218
- Tangent surfaces 322–323, 322–323
- Tap drills 656–657, 656–657
- Taper 541–542, 541–542
- Technical design 6–9, 32–79, 6–8, 32–79
- Technical drawing 6–8, 286–326, 6–8, 286–326
- Technical illustration (see also *Pictorial drawings*) 6–7, 12, 96–97, 6, 12, 96–97
- Technical illustrator 3–4, 6–7, 4–7
- Technical pen 134–136, 134–136
- Technical sketching 6–7, 250–277, 6–7, 250–277
- Templates 145–146, 145–146
 circle 145–146, 145–146
 electronic 12, 93, 12, 93
 lettering 174–197, 174–197
 piping 95–96, 95–96
- Terminal 83–85
- Text 174, 194–197, 194–197
- TEXT command 174, 194–197, 194–197
- Text font 174, 194–197, 194–197
- Text styles 174, 194–197, 194–197
- Threads 647–662, 647–662
 blind tapped holes 647–652, 647–652
 CAD 687–689, 647, 688–689
 designating 657–660, 658–661
 ACME 658–659
 buttress 659
 metric 659–660
 UN Forms 657–658
 dimensioning 539–570, 660–661, 539–569, 660–661
 drawing (see also *Thread representation*)
 653–657, 661, 653–657, 661
 ACME 655–656, 655–656
 detailed 653–657, 653–657
 schematic 653–655, 653–655
 simplified 653–654, 653–654
 chamfers 540–541, 660–661, 540–541, 660–661
 classes of 652
 engagement 650–651, 651
 external 647, 647
 fasteners (see also *Fasteners*) 658, 662–689, 658, 662–689
 fits 652
 classes of 652
 forms 647
 Acme 647–648
 American National 648, 648
 B&S worm thread 648, 648
 British Standard (Whitworth) 648, 648
 buttress 648, 648
 ISO metric 648–649, 649
 knuckle 648–649, 648
 sharp “V” 648, 648
 Unified National 648–649, 651–652, 647–649
 internal 647, 647
 lead 650–651, 651
 single, double, and triple
 650–651, 651
- notes (see also *Designating*) 528–529, 547–550, 657–660, 824–830, 528–529, 547–550, 658–661, 824–830
 parts 650, 650
 pictorial 661, 661
 pipe 661–662, 661–662
 relief (undercut) 647–660, 647–660
 representation 653–657, 653–657
 detailed 653, 653–657
 schematic 653–655, 653–655
 simplified 653–654, 653–654
 right-hand and left-hand 323, 650, 323, 651
 selection 652
 series 651–652
 tap drills 656–657, 656–657
 terms 649–650
- Three-view drawings 287–306, 287–306
- Third-angle projection 286–306, 286–306
- Title block tolerances 515
- Title blocks 149–150, 149–150
- Tolerances 515–517
- Tolerancing 575–635, 578–635
 accuracy 575–581
 actual size 517, 61–613, 612–613
 angular 526–528, 586, 526–528, 587, 588
 ANSI 576–635, 577–635
 basic dimension 517
 basic size 614–616, 614–616
 CAD 622–625, 633–635, 622–625, 633–635
 clearance fit 620–621, 620–621
 datums 551–552, 586–591, 586–591
 convenience 586–588
 feature 517, 586, 588–581, 588–591
 identification symbol 588–591, 588–591
 implied 588–591, 588–591
 partial 588–591, 588–591
 preference 587, 589–591, 588–591
 primary 587, 589–591, 589–591
 reference frame 586, 588–591, 588–591
 secondary 587–591, 588–591
 size 588–591, 588–591
 target 586, 588–591, 589–591
 tertiary 587, 588–591, 588–591
 deviation 551–555
 dimensioning 617–620, 617–620
 baseline 618, 618
 chain 617, 618
 direct 618, 618
 limit 619
 tapers 618, 618–619
 dimensions 619–620, 619–620
 basic 619, 620
 functional 619, 620
 non mandatory 619, 620
 reference 619, 620
 feature 517
 feature control frame 517, 583–586, 583–586

- feature of size 517
- formulas, positional
 - fixed fastener
 - floating fastener
- geometric dimensioning and tolerancing 576–635, 577–635
- geometric tolerances 551–552, 576–635, 577–635
 - form 591–607, 591–607
 - circularity 592, 597
 - cylindricity 592, 598
 - flatness 592, 596
 - straightness 591–592, 594–595
 - location 605–608
 - circularity 605
 - concentricity 607
 - position 608
 - orientation 609, 601–603
 - angularity 609, 601
 - parallelism 609, 603
 - perpendicularity 609, 602
 - profile 592, 609, 599–600
 - runout 592, 609–611, 599, 604–605
 - circular 592, 609, 600
 - patterns (positional) 611
 - position 610
- interference fit 620–621, 620–621
- least material condition (LMC) 584–586, 584–586
- limit dimensioning 616, 616
- limits and fits 620–635, 620–635
 - calculating 620–621, 628–633, 620–621, 628–633
 - clearance 620–621, 620–621
 - force 627, 627
 - hole basis system 629–630, 630
 - interference 620–621, 620–621
 - limits 620–621, 620–621
 - locational 543–546, 621, 626, 543–546, 626
 - metric 517–519, 629–631, 518–519, 630–631
 - preferred 621, 627–628, 627–628
 - Renard preferred numbers 620–621, 620–621
 - shaft limits 632–633, 632–633
 - shrink 627
 - single 620
 - tables 627, 627
 - tolerance zones 627–628
 - transition 620–621, 620–621
- limits of size 517, 611–614, 616, 611–614, 616
- lower deviation 616, 616
- maximum material condition (MMC) 581, 583–585, 582–585
- modifiers 581–583, 581–583
- nominal size 581–592
- plus and minus 620
- positional 628
- precision 581–592
- regardless of feature size (RFS) 582, 584–586, 582, 584–586
- role in industry 575–578
- symbols 537–540, 578–635, 537–540, 579–635
 - basic dimension 517, 537–540, 578–581, 537–540, 578–581
 - datum feature 517, 537–540, 578–581, 537–540, 578–581
 - datum target, 537–540, 578–581, 537–540, 578–581
 - depth 536–537, 579–581, 536–537, 579–581
 - diameter and radius 531–537, 578–581, 531–537, 578–581
 - dimension origin 537–540, 581, 537–540, 581
 - counterbore 537–540, 579–581, 537–540, 579–581
 - countersink 537–540, 579–581, 537–540, 579–581
 - geometric characteristics 578–581, 579–581
 - material condition 537–540, 578–581, 537–540, 578–581
 - spotface 537–540, 537–540
 - square 537–540, 581, 537–540, 581
 - tolerance zone 537–540, 578–581, 537–540, 578–581
- Taylor concept 576–577
- title block tolerances 515, 616–617, 616–617
- tolerances 515–517, 576–635, 577–635
 - accumulations 617–620, 617–620
 - bilateral 616, 620–621, 616
 - bonus 585–586
 - dimensioning 617–618, 617–618
 - geometric 584–586, 585–586
 - limits of size 616, 620–621, 616
 - positional 628
 - unilateral 616, 620621, 616
 - zone 628
- transition fit 620–621, 620–621
- true position 620–621, 620–621
 - upper deviation 620–621, 620–621
 - virtual condition 584–586, 585–586
- Tool design 480, 480
- Tool path simulation (see also *Cutter path and NC*) 13, 505–513, 13, 505–513
- Tooling 505–513, 840–851, 505–513, 840–851
- Track ball 88, 88
- Transition piece 840–851, 841–851
- Transportation engineering 10–12, 10–12
- Triangles 144–145, 201–202, 208, 144–145, 201–202, 208
 - 30/60 degree 144–145, 144–145
 - 45 degree 144–145, 144–145
 - adjustable 144–145, 144–145
- Trimetric axes 421–432, 421–432
- Trimetric projection 421–432, 421–432
- True shape/size 306–316, 306–316
- T-square 131–132, 132
- Turning 485–489, 485–489
- Turning speed 485–489, 485–489
- Two-view drawings 292, 296
- Units of measurement 14–15, 516–517, 516–527
 - SI 14–15, 516–517, 516
 - US 14–15, 517
- US Customary Unit 14–15, 517
- Vector analysis 1031–1059, 1031–1059
 - beam 1039–1044, 1039–1044
 - bridges 1036, 1036
 - graphical 1033–1048, 1033–1048
 - coplanar 1034–1035, 1037–1044, 1034–1035, 1037–1044
 - Maxwell diagrams 1044–1048, 1044–1048
 - noncoplanar 1051–1059, 1051–1059
- finite element analysis 1049–1051, 1049–1051
- terms 1032–1033
- trusses 1036, 1044–1048, 1036, 1044–1048
- Vellum 83–85
- Vernier calipers 490, 490
- View defining using CAD 287, 287, 295, 295
- View identification letters 351–352, 351–352
- VPOINT command 984–987, 984–987
- Views (see *Multiview projection*)
- VIEWPORT command 324–325, 324–325
- Visualization of views 311–313, 311–313
- Washers 671–673, 671–673
- Welded assemblies 780–802, 813–833, 780–802, 814–833
- Welding 780–802, 780–802
 - arrow 783–792, 783–792
 - backing bar 796–801, 796–801
 - brazing 781–785, 781–785
 - CAD 795–796, 795–796
 - drawings welding symbols 794, 794
 - joints 783–792, 783–792
 - laser 783, 783
 - materials 782–785, 782–785
 - methods 780–802, 780–802
 - arc welding 781–785, 781–785
 - gas-metal (MIG or GMAW) 781–785, 781–785
 - gas-tungsten (TIG or GTAW) 781–785, 781–785
 - shielded arc 781–785, 781–785
 - submerged arc 781–785, 781–785
 - fusion 781–785, 781–785
 - laser 781–785, 781–785
 - non-pressure 781–785, 781–785
 - pressure 781–785, 781–785
 - resistance 781–785, 781–785 °
- robots 99–100, 99–100
- spacers 785–795, 785–795

- Welding *continued*
 - spacers *continued*
 - symbols 783–785, 783–785
 - field weld designation 783–792, 783–792
 - melt-thru symbol 785–795, 785–795
- Weld-all-around symbol 783–792, 783–792
- Weld symbols 783–792, 783–792
- Weld types 780–802, 780–802
- Welds 783–785, 783–785
 - back (backing) 785–795, 785–795
 - bead 785–795, 785–795
 - fillet 796–801, 796–801
 - groove 785–795, 785–795
 - plug and slot 785–795, 785–795
 - projection 796–801, 796–801
 - seam 796–801, 796–801
 - surface (surfacing) 785–795, 785–795
- Whiteprint machine 132, 831, 132, 831
- WINDOWS software 82, 92
- WIP (work-in-progress) 81
- Wireframe model 83, 840–851, 83, 840–851
- Workpiece 812, 844–851, 812–813, 844–851
- Work-in-progress (WIP) 81
- Working drawings 810–850, 811–851
- Workstation 82–85, 83–85
- WORM optical disk 83–85, 83–85
- ZOOM command 566–567, 984–987, 566–567, 984–987
- ZOOM WINDOW command 566–567, 984–987, 566–567, 984–987

The following illustrations were rendered by artists at Precision Graphics:

Figure 1.03	<i>Chapter 8 Focus On . . . Geometry,</i>	14.26	19.09–19.10
1.11–1.13	page 210 (both figures)	14.27b	19.13–19.14
2.05	9.05–9.12	14.27c	19.17
2.13	9.15	14.32	19.23–19.24
2.21	9.18–9.19	14.38	19.29–19.31
2.24	9.21	14.46	19.37
3.02	9.23–9.25	14.47	19.39–19.40
3.04	9.30	15.51	20.07–20.19
3.06–3.08	9.33–9.34	15.86–15.90	21.01–21.11
3.11	9.37–9.38	15.99–15.100	21.13–21.24
3.13–3.14	9.44–9.46	15.102–15.105	22.03–22.05
3.16	10.04–10.11	15.107	22.07–22.08
3.20–3.21	10.17–10.21	16.02–16.30	22.11
3.23–3.24	10.23–10.39	16.34–16.37	23.26
3.26–3.32	10.41–10.57	16.49–16.52	23.33
3.36	10.63	<i>Chapter 16 Applying Parametric</i>	24.03–24.04
3.41	10.65	<i>Design . . . Tolerancing and</i>	24.07
3.56	11.07	<i>Parametric Features,</i> pages 622,	24.09
3.58	11.15–11.17	624, and 626 (Figures A, B, C, J,	24.13
3.62	11.25	N, and O)	24.24
5.05	11.29–11.33	Problems 16.05– Problem 16.12	25.06
5.16	11.36 (top diagrams)	17.11	25.08
5.17a (flow chart)	11.37–11.38	17.14–17.20	26.01c and d
5.28	12.03–12.09	17.26	27.06
6.12	12.15	17.31	27.19a
6.16	12.21–12.22	17.85	27.24
6.19–6.21	13.09	<i>Chapter 17 Applying Parametric</i>	<i>Chapter 27 Focus On . . .</i>
6.24–6.25	13.13–13.16	<i>Design . . . Standard Part Families</i>	<i>Constructive Solid Geometry (CSG),</i>
6.28–6.33	13.18–13.26	<i>and Cosmetic Fastener Threads,</i>	page 980
6.42–6.43	13.29–13.31	page 677 (Figures L and M)	28.03
6.53–6.69	13.33–13.42	18.02–18.03	28.05
7.03–7.04	13.49–13.50	18.05	28.25
7.07	13.56–13.57	18.08	29.02–29.03
7.10–7.18	13.59	18.11	29.23
7.33–7.36	13.63	18.13	29.32–29.33
<i>Chapter 7 Applying Parametric</i>	13.66–13.73	18.15	<i>Chapter 29 Focus On . . .</i>
<i>Design . . . Text and Notes on Models</i>	13.75–13.76	<i>Chapter 18 Focus On . . . Spring</i>	<i>Magnificent Iron Bridges,</i> page
<i>and Drawings,</i> page 193 (Figures D	14.04–14.05	<i>Designs Drawn from Tooling</i>	1036
and E)	14.07	<i>Libraries,</i> page 697 (top left)	30.16
8.02–8.04	14.13	19.02	30.26
8.06–8.45	14.24c	19.04–19.07	Appendix C, page A-79
8.46a			
8.47–8.64			

Photo and Illustration Credits




Figure numbers precede each credit line. Materials credited to Autodesk are reprinted with the permission from and under the copyright of Autodesk, Inc. Copyright © 1995 Autodesk, Inc.

Chapter 1. Figure 1.01 Hewlett Packard

- 1.02 Hewlett Packard
- 1.04 Computervision
- 1.05 Lockheed
- 1.07 Parametric Technology Corp.
- 1.09 Gary Donaldson
- 1.10 Lockheed
- 1.14 Lockheed
- 1.17 J. I. Case Corporation
- 1.20 Chicago Bridge and Iron Co.
- 1.22 NASA
- 1.23 © Richard R. Hansen/Photo Researchers
- 1.24 American Switch Business
- 1.25 Adage, Inc.
- 1.29 Evolution Engineering
- 1.30 Lockheed
- 1.31 Aero Gear
- 1.32 Autodesk

Chapter 1 Focus on . . . *The Design Process*, page 8 (left), courtesy of Levi-Strauss, and (right) © Tony Freeman/PhotoEdit

Chapter 2. 2.01a Autodesk

- 2.01b Drawn with AutoCAD® 3D Studio
- 2.02 Parametric Technology Corp.
- 2.03a Logitech
- 2.03b–2.03c Parametric Technology Corp.
- 2.06 Stanford Physics Lab, Palo Alto
- 2.07 Lockheed
- 2.10 © Tony Freeman/PhotoEdit
- 2.11 Autodesk
- 2.17 © Tony Freeman/PhotoEdit
- 2.18 © Photri
- 2.19 NASA (1977)
- 2.25–2.28 Lockheed
- 2.30–2.32 Lockheed
- 2.33–2.34 Gary Donaldson/Lockheed
- 2.35–2.36 Lockheed

Chapter 3. 3.01 Autodesk

- 3.09–3.10 Grove Valve and Regulator Company

- 3.15 Macola, Inc.
 - 3.17 NASA
 - 3.18 Engineering Model Associates, Inc.
 - 3.19 Magee-Bralla, Inc.
 - 3.35 © UPI/Bettmann
 - 3.37–3.38 © Photri
 - 3.39 NASA
 - 3.40a Silverscreen
 - 3.40b © Ross Harrison Koty/Tony Stone Images
 - 3.42–3.44 NASA
 - 3.46 Model by Continental Engineering
 - 3.48 Megatek Corp.
 - 3.49 CADKEY, Inc.
 - 3.50 Gibbs and Associates
 - 3.52 Computervision
 - 3.53 © Calma, a division of Prime Computer
 - 3.59 Computervision
 - 3.63c Innovative Design Systems Corp.
 - 3.64a © 1994 Logitech, Inc.
- Chapter 3 Focus On . . . *Stereolithography in the Design Process*, page 57, courtesy of Motorola

Chapter 4. 4.01 Hewlett Packard Co.

- 4.02 Cincinnati Milacron
- 4.03 CADKEY, Inc.
- 4.04 Lockheed
- 4.05 Cincinnati Milacron
- 4.06 CADKEY, Inc.
- 4.07–4.08 Hewlett Packard Co.
- 4.09 Control Data Systems, Inc.
- 4.10 © Apple Computer, Inc. All rights reserved. Used with permission. Apple® and the Apple logo are registered trademarks of Apple Computer, Inc.
- 4.11–4.12 Hewlett Packard Co.
- 4.13 ISICAD, Inc.
- 4.17 © 1994 Logitech, Inc.
- 4.18 Hewlett Packard Co.
- 4.19 Computervision
- 4.20–4.24 Hewlett Packard Co.
- 4.25 IBM
- 4.26 Computervision
- 4.27 Intergraph Corp.
- 4.28 Autodesk
- 4.30 McDonnell Douglas
- 4.31 Drawn using American Small Business Computers' DesignCAD 3D

- 4.32a Vector Automation-
- 4.32b Macola, Inc.
- 4.33a Drawn using American Small Business Computers' DesignCAD 3D
- 4.34 Hewlett Packard
- 4.36 IBM
- 4.37 Drawn using American Small Business Computers' DesignCAD 3D
- 4.38 CADKEY, Inc.
- 4.39a Drawn using American Small Business Computers' DesignCAD 3D
- 4.39b CADKEY, Inc.
- 4.40 CAMAX Systems, Inc.
- 4.41–4.43 Cincinnati Milacron
- 4.44 Ford Motor Co.
- 4.45 © Simon Fraser, Newcastle Library/Photo Researchers
- 4.46 Evans & Sutherland Computer Corp.

Chapter 5. 5.01 Parametric Technology Corporation

- 5.02–5.04 Parametric Technology Corp.
- 5.12–5.13 Parametric Technology Corp.
- 5.18 Parametric Technology Corp.
- 5.25–5.27 Parametric Technology Corp.
- 5.29 Parametric Technology Corp.
- 5.36–5.39 Parametric Technology Corp.

Chapter 6. 6.01 Koh-I-Noor

- 6.02 © The Image Works
- 6.03 © Peter Menzel/Stock Boston
- 6.04–6.05 3M Company
- 6.07 Koh-I-Noor
- 6.08 Staedtler, Inc.
- 6.09 VEMCO
- 6.10 Staedtler, Inc.
- 6.13 Berol RapiDesign
- 6.14–6.15 Koh-I-Noor
- 6.17 Staedtler, Inc.
- 6.18 Koh-I-Noor
- 6.22–6.23 Staedtler Inc.
- 6.26 © J. Pickerell/The Image Works
- 6.27 Koh-I-Noor
- 6.35 © Bob Daemrrich/Stock Boston
- 6.36 Hearlihy & Co.
- 6.37–6.38 Koh-I-Noor
- 6.39 Staedtler, Inc.
- 6.40 VEMCO
- 6.41 Koh-I-Noor
- 6.44 K & E

- 6.45 Staedtler, Inc.
 6.46–6.49 Koh-I-Noor
 6.50–6.52 ANSI
 6.70 Staedtler, Inc.
 6.71 Koh-I-Noor
- Chapter 7.** 7.09 Koh-I-Noor
 7.21 Staedtler, Inc.
 7.23 Staedtler, Inc.
 7.26 Arnold & Brown
 7.27–7.28 Kroy, Inc.
Chapter 7 Focus On . . . The Alphabet, page 186 and page 187 (left) © North Wind Picture Archives, and page 187 (right) © Michael Newman/PhotoEdit
- Chapter 8.** 8.01a Lockheed
 8.01b © Joseph Nettis/Photo Researchers
 8.01c Intergraph
- Chapter 9.** 9.51 Computervision
Chapter 9 Focus On . . . Leonardo Da Vinci, The Sketcher, page 256 (left and right), © North Wind Picture Archives
- Chapter 10.** 10.01 Lockheed
 10.02 Autodesk
Chapter 10 Focus On . . . Evinrude, page 303 (left and right), courtesy of Outboard Marine Company
- Chapter 11.** 11.02a Lunkenheimer Corp.
 11.45 Control Data Corp.
 11.46 © Alan Levenson/Tony Stone Images
Chapter 11 Focus On . . . Ultrasound, page 352, courtesy of Techsonic Industries
- Chapter 12.** *Focus On . . . Hand Tools and Devices*, page 389, © Michael Newman/Photo Edit
- Chapter 13.** 13.04 Lockheed
 13.05–13.06 Autodesk
 13.07–13.08 Parametric Technology Corporation
 13.64 SmartCAM/CAMAX Manufacturing Technologies
 13.79 Parametric Technology Corporation
 13.84 Autodesk
Chapter 13 Focus On . . . Pictorials, page 433 (top right), © North Wind Picture Archives, and (bottom left, middle, and right) © Autodesk
- Chapter 14.** 14.03 Lockheed
 14.06a Lockheed
 14.06b Cogsdill Tool Products, Inc.
 14.08 Lockheed
 14.10 Cogsdill Tool Products, Inc.
 14.11 © Michael Rosenfeld/Tony Stone Images
 14.14 Cogsdill Tool Products, Inc.
 14.16 © Photri
 14.17 © Will & Deni McIntyre/Photo Researchers
- 14.18 © Holt Confer/The Image Works
 14.20 © 1995 Terry Wild Studios
 14.21 Aero Gear
 14.22 Mitutoyo/MTI Corp.
 14.23 © 1995 Terry Wild Studios
 14.28 Parametric Technology Corporation
 14.37 Aero Gear
 14.39 Parametric Technology Corporation
 14.42 Cogsdill Tool Products, Inc. of Camden, SC
 14.43 Control Data Systems Inc.
 14.44 Vericut by CGTECH
 14.45 D. P. Technology Corp.
 14.48 D. P. Technology Corp.
 14.49–14.50 SmartCAM/CAMAX Manufacturing Technologies
- 14.52a Cincinnati Millicron
 14.54 Evans & Sutherland
Chapter 14 Focus On . . . Computers in Manufacturing, page 489 (top right), courtesy of Ford Motor Company, and (bottom left) © Benelux/Photo Researchers
Chapter 14 Applying Parametric Design . . . Parametric Models and Machining, page 500, courtesy of Parametric Technology Corporation
- Chapter 15.** 15.01a and b D. P. Technology Corporation
 15.01c Lockheed-California Co.
Chapter 15 Focus On . . . The History of the Metric Standard, page 533, © The Bettmann Archive
- Chapter 17.** 17.04 D. P. Technology Corporation
 17.34 Federal Screw Products
 17.47 Holo-Krome©
- Chapter 19.** 19.01 Aero Gear
 19.03 D. P. Technology Corp.
 19.08 Aero Gear
 19.35 Hewlett-Packard Co.
 19.38 FAG Bearing Corp.
 19.41–19.42 The Timken Company
 19.43–19.44 FAG Bearing Corp.
Chapter 19 Focus On . . . Elevators, page 718 (left) © The Bettmann Archive, and (right) © Robert Brenner/PhotoEdit
- Chapter 20.** 20.02a © Tony Freeman/PhotoEdit
 20.03 Commercial Cam Company, Inc. (CAMCO)
Chapter 20 Focus On . . . Engine Camshafts, page 747, © D. Miliano/Photri
- Chapter 21.** *Chapter 21 Focus On . . . Piping Systems*, page 766 (left), © The Bettmann Archive, and (right) © Copyright 1994 George Haling/Photo Researchers/All rights reserved
- Chapter 22.** 22.01 © Bruce Forster/Tony Stone Images
Chapter 22 Focus On . . . Using the Laser to Weld, page 783 (bottom left) © James Holmes/Rover/Science Photo Library, and (top right) © Photri
- Chapter 23.** 23.01 Parametric Technology Corporation
 23.03 NASA
 23.06 Grove Valve and Regulator Company
 23.09 FAG Bearing Corp.
 23.12 IBM
 23.23 © Tom Hollyman 1979/Photo Researchers
 23.24–23.25 3M
 23.27 IBM
 23.28 Autodesk
 23.29 CADKEY, Inc.
 23.32 IBM
 23.35 Gerber Systems Technology, Inc.
 23.37 Carr Lane
 23.38 Wedge Innovations
Chapter 23 Focus On . . . America's First Automobile, page 820, courtesy of Ford Motor Company
Chapter 23 Applying Parametric Design . . . Assemblies, Exploded Assembly Models, and Reports (BOM), page 832 (Figures A and B), courtesy of Parametric Technology Corporation
- Chapter 24.** 24.34 Louis Gary Lamit
- Chapter 26.** 26.01 © SERAPID, Inc.
 26.21 PATRAN, a division of PDA Engineering/MacNeal-Schoendler Corporation
 26.23 PATRAN, a division of PDA Engineering/MacNeal-Schoendler Corporation
Chapter 26 Focus On . . . The Gyrocompass, page 947, courtesy of Sperry Marine
- Chapter 27.** 27.01b IBM
 27.02 Lockheed
 27.18 CADKEY, Inc.
 27.22 Lockheed
 27.30–27.31 CADKEY, Inc.
- Chapter 28.** 28.02b Lockheed
 28.30 © John Coletti/Stock Boston
Chapter 28 Focus On . . . Packaging, page 1005, © Michael Newman/PhotoEdit
- Chapter 29.** 29.01 © David R. Frazier Photolibrary/Photo Researchers
 29.42 © John Keating 1981/Photo Researchers
Chapter 29 Focus On . . . Magnificent Iron Bridges, page 1036 (top right), © Brian Yarvin 1994/Photo Researchers